1/11





Fig. 1

2/11






Fig.2b




Fig. 3




Fig. 5






Fig. 4





Fig. 6







Fig. 8



8/11




Fig. 10




Fig. 11






Fig. 12





Fig. 13



HEICHT OF RIM FLANGE (INTERIOR SIDE OF VEHICLE)